

Is'bad →

OCT 23 6 02 AM '90

STAT

Approved For Release 2007/09/25 : CIA-RDP84-00868R000100050130-6

HAS MAKING CONTACT WITH THE FRAME AND FRICTION CAUSED
A HOLE IN THE FILTER. THE JEEP IS NOW AT THE MOTOR
POOL AND WE HAVE RENTED ANOTHER VEHICLE UNTIL REPAIRS
CAN BE MADE TO THE JEEP.

2, PLEASE PROCURE AND FOUCH SOONEST THE FOLLOWING
PARTS: THREE EACH OIL FILTERS (TWO ARE FOR SPARES);
ONE EACH MOTOR MOUNT, PART NO. 6F3223023; ONE EACH
MOTOR MOUNT PLATE, PART NO. CAL-1-5351784. WE WILL
ALSO NEED THREE EACH MOUNTING BOLTS FOR THE MOTOR
MOUNT PLATE. IN ADDITION WE WILL NEED ONE EACH OVERSIZE
BOLT, 7/16 INCH X 1-3/4 INCH. THE BOLT HOUSING ON THE
MOTOR BLOCK IS CHIPPED AND WE MIGHT HAVE TO DRILL AND
RETAP THE HOLE FOR A LARGER BOLT; WE BELIEVE THERE IS
ENOUGH THREAD FOR THE PROPER BOLT, BUT WE ARE ORDERING
AN OVERSIZE BOLT JUST IN CASE. SERIAL NUMBER OF THE
6-CYLINDER JEEP CHEROKEE IS JOM16NC003095.

3, A COMPLETE LIST OF THE FURNITURE AND OFFICE
EQUIPMENT RECEIVED WILL BE FURNISHED IN A
SEPARATE MESSAGE,

BT

#2907

STAT

NNNN